



Release Notes

AGRICULTURE

January 2019

Version A

TRIMBLE RESELLER CONFIDENTIAL

CFX-750 Display: Firmware Version 7.78

The latest Trimble® Agriculture CFX-750™ display system release was created to address reported quality issues around CenterPoint RTX not operating in certain coastal regions.

Who Should Upgrade Now

This firmware introduces new features and addresses very specific issues that have been reported in the field. You should consider upgrading to version 7.78 from earlier versions if:

| Installed Version | Upgrade To |
|--|---|
| Any version earlier than 7.78 | Version 7.78. This version includes the fixes to the reported field issues outlined below. |
| Version 7.77, where you <i>do not</i> experience the issues outlined. | No upgrade needed. Unless you encounter any of the issues outlined below. |

The firmware and language packs are available to be installed via USB. You can download the latest firmware and language packs from [Trimble Partners](http://agpartners.trimble.com).

Notes:

- Display User Data should always be backed up before a firmware update is started.
- Display should be rebooted after a firmware updated, and before work is started.

<http://agpartners.trimble.com>

www.trimble.com

© 2019, Trimble Inc. All rights reserved. Trimble, the Globe & Triangle logo, Autopilot, EZ Pilot, EZ Steer, Field-IQ, and CFX-750 are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.

Version Compatibility

Once you apply the firmware update, refer to the following table for a summary of updated components:

| CFX-750 Display System Components | Minimum Version Requirements |
|-----------------------------------|---|
| Language Packs | |
| Language Packs | 7.78.002.4 |
| Autopilot | |
| NavController | 13.00 or higher |
| EZ Pilot | |
| IMD-600 | 2.01 |
| SAM-200 | 1.04 |
| EZ Steer | |
| SCM T2 | 4.01.00 |
| Modem | |
| DCM-300 | 7.4.6 |
| Field-IQ | |
| Master Switch Box | 3.06 |
| 12 Section Switch Box | 3.06 |
| Section Only Module | 3.05 |
| Rate and Section Module | 3.20 Note: Version 4.13 and higher is not compatible with this release. |
| Signal Input Module | 3.06 |
| Seed Monitor Module | 2.06 |
| Yield Monitoring | |
| Yield Monitoring Module | 1.23 |
| Moisture Sensor Module | 1.14 |

Note: Guidance, Field-IQ, and Yield Monitoring module firmware is not included in the CFX-750 firmware image, and must be downloaded separately from the appropriate Partners locations. (See Trimble Ag. Partners > Display Type > Software Downloads for the required files.)

Firmware Version 7.78 Enhancements and Bug Fixes Summary

The following section summarizes bug fixes included with the release of firmware version 7.78.

CenterPoint RTX and RangePoint RTX would not operate in certain coastal regions

A bug was introduced in CFX 7.75 and remained in CFX 7.76 and CFX 7.77, where CenterPoint RTX and RangePoint RTX would not operate in certain coastal regions. This bug is fixed in CFX 7.78.

For More Information

Contact your local Trimble Regional Sales Manager.